



SERVICE BULLETIN

SB No. 55 Issue No. 4

TITLE

SPECIAL INSPECTION OF THROTTLE CABLE - T67 160/200 HP AIRCRAFT

CLASSIFICATION

This Service Bulletin has been classified as Mandatory by the U.K. C.A.A.

COMPLIANCE

This Service Bulletin must be carried out before next flight and subsequently at 25 flying hour intervals until Mod M496 is incorporated.

With reference to Issue 3:

The following statement amended:

"Mandatory Modification M496 must be incorporated not later than March 31st 1995".

Date was January 31st 1995.

Enclosure: Service Bulletin SB No.55 Issue 3, if required.

ISSUED
25 JAN 1995

ISSUED BY:



Date 25-1-95

for and on behalf of **SLINGSBY AVIATION LIMITED**
Kirkbymoorside, York YO6 6EZ England Tel 0751 32474 Telex 57597

Page 1 of 1